

July 2010: Will your Pin Pad become obsolete?

The following pin pads will not be compliant and ***should not be used as of July 2010***. Replacements will be required.

Hypercom S8; Hypercom S9; Pin Pad 1000SE (model number P003-170-02 & P003-160-02); **Nurit 222; Nurit 292**

The following equipment is compliant ***if it has been TDES encrypted***. Validate the TDES encryption by checking the label on the bottom of the pin pad. It should indicate TDES.

Hypercom P1300 (model number P1300-010248-001)

S9PCI (model number 010340-003R)

Pin Pad 1000SE (model number P003-180-02 & P003-180-03)

N8400-11; N8020-11; N8400-43; Vx510 (model number M251-000-33-NAA)

Vx510LE (model number M251-000-33-NAB)

Vx570 (model number M257-000-02-NAA, dial only; model number M257-050-02-NAA; model number M257-503-02-NAA dial only with smart card; model number M257-556-02-NAA)

Hypercom T4205 (model number 010344-001R) **Hypercom T4210** (model number 010332-311R)

Hypercom T4220 (model number 010332-306R)

Please contact your agent representative for assistance in purchasing a compliant pin pad. If you have additional questions, please call your local representative or processor.

